

11044 31 OCT 64

SECRET

TO : DIRECTOR

FROM :

25X1A

ACTION:

INFO :

TOR: 1222Z 31 OCT 64

PRIORITY

IN 55368

OPS 1-742

TO : PRIORITY

INFO

5912 25X1A

25X1A
25X1A

0240/310229Z/352

25X1A

1. 852/5

2. 66

3. LIGHT ACTIVITY BANDS 1 AND 2, NO SIGNALS BAND 3, WILL CHECK FURTHER.

25X1A

1. 812/754/NA/NA/NA/NA/NA/2018

2. 100

3. LIGHT ACTIVITY X, S AND L BANDS, HEAVY ACTIVITY

25X1A


F BAND. TIMER APPARENTLY FAILED, CHECK SHOWED SWITCH IN BOTH, WILL CHECK FURTHER.

25X1A

1. NA

2. NO ACTIVITY

25X1A



[] 5912 (IN 55368)

S E C R E T

PAGE TWO

25X1A

1. NA
2. NO ACTIVITY

[]

25X1A

1. NA
2. DRIVER REPORTED RECEIVER LIGHT FLICKERED THROUGHOUT MISSION.

[] OPERATION SATISFACTORY

25X1A

RADIO AND NAV AIDS OPERATION SATISFACTORY

END OF MESSAGE

S E C R E T